



# West Yorkshire Materials Testing Service

PO Box 5, Morley, LS27 0QP  
Nepshaw Lane South, Morley, Leeds  
Tel 0113 253 0241 Fax 0113 252 7029  
Head of Laboratory G. Briggs C. Text ATI

Client:

Acolade

KST 6287 FR

**Entry No:** 32293 -01 (Amended)  
**Date received:** 12/02/2007  
**Client's Description:** Sample of modacrylic/polyester dimout fabric:- B -6287

## TEST REPORT

**Test Required:** Flammability BS 5867 : Part 2 : Type B  
**Pre-treatment:** 12 washes in accordance with BS5651 : 1978 Commercial Laundry Procedure 40  
**Conditioning:** A minimum of 24 hours at 60 +/- 5% Relative Humidity, 20 +/- 5°C  
**Method of Test:** BS 5438 : 1976 Test Method 2 as modified by BS 5867 : Part 2  
**Date of Test:** 20/02/2007

The results may not apply to situations where there is restricted air supply or prolonged exposure to large sources of intense heat as in a conflagration.

### Flame application time 15 seconds

No part of any hole or the lowest boundary of any flame reached the upper edge or either vertical edge on any specimen. There was no separation of flaming debris from any specimen.

### Comments

On the basis of the tests carried out this sample of fabric meets the Type B requirements of BS 5867 : Part 2 : 1980.

-----End of Document-----

*This is hereby certified to be a correct return of the tests made of the items referred to herein.*

G Briggs, Head of Laboratory  
Date of original 21<sup>st</sup> February 2007  
Date of amendment 26<sup>th</sup> April 2007

Unless instructed otherwise by the client sample remnants will be disposed of after 28 days.

- \* Test marked (\*) in this certificate are not included in the UKAS Accreditation Schedule for this Laboratory.
- \* Opinions and interpretations expressed herein are outside the scope of UKAS accreditation.
- \* This Certificate relates only to the sample received and, unless that sample has been drawn by the staff of this laboratory, or its agent, and endorsed accordingly, any application of the result to a bulk quantity or other material is entirely the responsibility of the client.



1104